

Safety Experience

Inadvertent overhead panel switches activation when using sun visor



Potential effects

- Loss of ADIRS
- RAT deployment
- Loss of some flight envelope protections

Recommendations

- (Handle sun visor with care
- Report cases of free rotation of ADIRS switches
- Remain mindful of inadvertent control activation inside the cockpit
- In case of inadvertent switch activation, follow ECAM and QRH checklists with active crosscheck during recovery procedures
- Report any anomalies on cockpit control







